



Colorado Department
of Public Health
and Environment

ASBESTOS CONSULTING FIRM

This certifies that

Herron Enterprises USA, Inc.

Registration No.: ACF - 14976

has met the registration requirements of 25-7-507, C.R.S. and the Air Quality Control Commission Regulation No. 8, Part B, and is hereby authorized to perform asbestos consulting activities as required under Regulation No 8, Part B, in the state of Colorado.

Issued: January 30, 2014

Expires: January 30, 2015

Authorized APCD Representative

SEAL



2761 West Oxford Avenue #7
Englewood, CO 80110
(303)781-0422

CERTIFIES THAT

BILLIE J. HERRON-LUSK

has successfully completed the


EPA-APPROVED AHERA ANNUAL REFRESHER COURSE for **INSPECTOR/MANAGEMENT
PLANNER** and passed the required examination in that discipline.

This course is EPA-approved under Section 206 of the Toxic Substance Control Act (TSCA)

Course Date 07/10/13
No. of hours 8
Certificate No. DR071013 - 09AM
Expires 07/10/14



Authorized Signature



Invalid without raised seal





Colorado Department
of Public Health
and Environment

ASBESTOS CERTIFICATION*

This certifies that

Billie J. Herron-Lusk

Certification No.: 2650

has met the requirements of 25-7-507, C.R.S. and Air Quality Control
Commission Regulation No. 8, Part B, and is hereby certified by the
state of Colorado in the following discipline:

Inspector/Management Planner*

Issued: October 29, 2013

Expires: October 29, 2014

** This certificate is valid only with the possession of a
current Division-approved training course certification
in the discipline specified above.*

Authorized APCD Representative

SEAL



COLORADO HAZARD CONTROL LLC

1775 West 55th Avenue
Denver, CO 80221
303.410.4941

36 North Research Drive, Suite B
Pueblo West, CO 81007
719-225-0283

Certifies that

Michael Herron

*Has Successfully Completed the EPA- Approved Asbestos Initial Training Course
Under Section 206 of the Toxic Substance Control Act (TSCA), Title II.*

In:

BUILDING INSPECTOR

Course Date: November 25-27, 2013
Number of Hours: 24
Certificate No.: 113389
Expiration Date: November 27, 2014


Frank Hulce – Training Instructor


Danaya Benedetto -- Training Program Manager





Colorado Department
of Public Health
and Environment

ASBESTOS CERTIFICATION*

This certifies that

Michael W. Herron Sr.

Certification No.: 13788

has met the requirements of 25-7-507, C.R.S. and Air Quality Control
Commission Regulation No. 8, Part B, and is hereby certified by the
state of Colorado in the following discipline:

Building Inspector*

Issued: December 06, 2013

Expires: December 06, 2014

** This certificate is valid only with the possession of a
current Division-approved training course certification
in the discipline specified above.*

Authorized APCD Representative

SEAL

ATTACHMENT B
STAGE I FIELD DOCUMENTATION

WIPE SAMPLING



URS Corporation
8181 E. Tufts Ave,
Denver CO 80237

MOLINE STAGE I INVESTIGATION
Wipe Sample Documentation Form
Project Number
41569671

Project Contact
Geoffrey Uhlemann
Phone: 303.803.8964

Page 1
of 1

ran Aroclor-1242
PCB/Chloride $\frac{mg}{100cm^2}$

Sample #	Sample ID	Sampler Initials	Date	Time	Height (feet)	Dexsil Field Kit PCB Results $\frac{mg}{100cm^2}$	Confirmation Sample Sent to Lab? (Y/N)	QC?
1	D-C1-15.5	GW	2/24/13	0945	15.5	763 / 320	Y	—
2	D-C1-15.5-FD			0945		2406 / 1010	—	Field FD
3	D-C1-15.5-Lab			0945		13 —	Confirmation	
4	D-W1-5			1020	5	779 / 335	—	—
5	D-F1-0			1025	0	1115 / 468	—	basin city sample
6	B-C1-13.5			1035	13.5	1315 / 552	—	offly Fixture
7	B-W1-2			1045	2	114 / 48	—	west wall
8	B-F1-0			1050	0	1998 / 838	—	NW corner
9	C-C1-11			1055	11	374 / 157	—	
10	C-W1-4			1100	4	1787 / 780	Y	southwest
11	C-W1-4-Lab			1100	4	0.42 —	Confirmation	
12	C-F1-0			1105	0	1164 / 2306	—	SW corner
13	C-TANK			1135	2	1145 / 481	—	pressure tank
14	E-C1-12.5			1145	12.5	229 / 963	—	
15	E-W1-4			1150	4	78.9 / 33.1	—	north
16	E-F1-0			1155	0	2000 / 840	—	
17	F-C1-12			1205	12	73.9 / 31.0	—	on heater
18	F-W1-3			1210	3	78.3 / 32.9	Y	north
19	F-W1-3-Lab			1210	3	0.38 —	Confirmation	
20	G-C1-9			1220	9	349 / 146	—	air duct exposed
21	G-W1-4			1225	4	11.7 / 4.93	—	western hallway
22	G-F1-0			1230	0	59.4 / 24.9	—	hallway tile
23	H-C1-12.5			1235	12.5	16.0 / 6.73	—	
24	H-W1-4			1240	4	42.3 / 17.7	Y	southern wall
25	H-W1-4-Lab			1240	4	57 —	Confirmation	
26	H-F1-0			1245	0	629 / 264	—	
27	I-C1-16.5			1250	16.5	15.2 / 6.41	—	
28	I-W1-4			1255	4	9.65 / 4.05	—	
29	I-F1-0			1300	0	815 / 342	Y	
30	I-F1-0-Lab			1300	0	5.4 —	Confirmation	
31	I-F1-0-FD			1300	0	408 / 171	—	Field screen FD
32	F-F1-0			1305	0	272 / 114	—	
33								
34								
35								

Additional General Notes:

2% in lab, 5% field FD (not lab), 3% of lab = top tank
* Consistently fresh from most readily stained surface; also collected two soil samples from building C

Lab results reported in mg/wipe